## **GUJARAT TECHNOLOGICAL UNIVERSITY**

	RF	- SEMESTER-III (NEW) - EXAMINATION – SUMM	FR 2017
Subject			Date: 09/06/2017
U			atc. 07/00/2017
Subject Name: Manufacturing and Assembly Drawing			
Time: 10:30 AM to 01:00 PMTotal Marks: 7			
Instruction			
		pt all questions. suitable assumptions wherever necessary.	
		es to the right indicate full marks.	
	8		MARKS
Q.1		Short Questions	14
Q.1	1	What is the use of Riveting?	14
	2	Define Tolerances.	
	3	Draw the symbol for Straightness	
	4	Write three non-ferrous material name.	
	5	Draw the symbol of a Profile of Surface	
	6	Draw the symbol of Square Butt weld	_
	7	Draw the conventional for Leaf spring	
	8	Draw the conventional for Bevel Gear	
	9	Draw the symbol for Fillet weld	
	10	Draw the symbol for Spot weld	
	11	Write the abbreviation for Material	
	12	Draw the symbol for angularity	
	13	Write the abbreviation for Assembly	
	14	Draw the symbol of Profile of a line	
Q.2	<b>(a)</b>	Define Fit.	03
-	<b>(b)</b>	Explain about alloy cast irons.	04
	(c)	Explain and compare "Hole basis system" and "Shaft basi system" of fits. From manufacturing point of view which system is preferred? Why?	
	$(\cdot)$	OR	. 07
	(c)	What is "alloying"? Explain the effect of adding following alloying element on steel (i) Mn (ii) Si (iii) Cr (iv) Mo (v) T (vi) W.	-
Q.3	<b>(a)</b>	Differentiate between Lap Joint and Butt Joint.	03
	(b)	Explain Ra Value and Roughness Grade Number.	04
	(c)	Brass and Bronze are alloys of which non-ferrous material Give composition and application of (i) Cartridge Brass (ii Gun Metal (iii) Muntz Metal.	
		OR	
Q.3	(a)	Differentiate between chain riveting and zig - zag riveting.	03
	<b>(b)</b>	Give brief classification of ferrous metals.	04
	(c)	Draw the convection for the following (i) External Thread (ii Spur gear (iii) Leaf Spring (iv) Spiral Spring (v) Trapezoida section (vi) Knurling (vii) Chain wheel	
Q.4	(a)	Define Production drawing of a component. What is the	e <b>03</b>
	<b>(b</b> )	importance of Production drawing? What is the importance of surface roughness?	04
	(D) (C)	Write a short note on copper and copper alloys.	04 07
	-		

## OR 0.4 What is an injection mould? 03 **(a)** What are the different parts of an Injection mould? 04 **(b)** The dimensions of a shaft and hole are: Basic Shaft size =6007 **(c)** mm and given as $60^{-0.02}$ & Basic hole size =60 mm and given as 60 -0.005 find i) Tolerance of Shaft, ii) Tolerance of Hole, iii) Max Allowance, v) Min allowance, iv) Type of Fit. Q.5 Write the effects of adding alloying elements Cr to steels. 03 **(a) (b)** Draw any FOUR elementary welding symbols with its 04 designation and illustration.

(c) What is production drawing of a component? What information must be provided on production drawing of a machine to facilitate its manufacturing and assembly?

## OR

Q.5 The component parts of a Lathe Tail Stock are shown in 14Figure 1. Prepare the front view in section of the assembly.




Figure 1.

\*\*\*\*\*\*