Seat No.:	Enrolment No.

## GUJARAT TECHNOLOGICAL UNIVERSITY

BE - SEMESTER-VII • EXAMINATION - SUMMER • 2014 Subject Code: 172501 Date: 22-05-2014 **Subject Name: Computer Aided Manufacturing** Time: 02.30 am - 05.00 pm **Total Marks: 70 Instructions:** 1. Attempt all questions. 2. Make suitable assumptions wherever necessary. 3. Figures to the right indicate full marks. (a) 0.1 Compare conventional machines, NC and CNC. 07 Classify and explain robot configurations with neat sketches. 07 **(b)** 0.2 (a) Draw and discuss various aspects of CIM WHEEL. 07 What are the different types of NC system based on motion control? **07 (b)** List and discuss various components of NC system. 07 Write the steps to identify the axes of CNC Lathe, milling and drilling machine with `Q.3 (a) 07 neat sketch. Explain Subroutine, Do loop and Macro with suitable examples. 07 **(b)** OR Q.3 Explain factors to be considered while designing the structure of CNC machines. **07** (a) Using G and M codes prepare CNC Part programme for the figure-I. Take raw **(b)** 07 material size as  $\emptyset$  45 X 100 mm length. Assume suitable cutting parameters. 8 20 NOTE: ALL DIMENSIONS ARE IN mm. Figure-I **Q.4** What is the need for CAPP? What are the various considerations for CAPP system **07** (a) implementation? Explain advantages of CAPP over conventional process planning. How do you justify the use of robot? Identify the five manufacturing situations **07 (b)** which are suitable for robot applications. Justify your answer. 0.4 Define Mechatronics. Discuss various elements of Mechatronics. 07 (a) Write short note on "Selective Laser Sintering" technique of RPT. **(b) 07** What is Group Technology? Explain various classification and coding system of GT. Q.5 07 (a) What is Automated Guided Vehicles? Explain different types of AGVs with their **07 (b)** 

advantages and limitations.

**Q.5** 

(a)

**(b)** 

example.

Explain the function of various components of FMS.

What is cutter radius compensation? Why it is required? Explain by taking a suitable

1

07

07

## List of G- and M-Codes.

- G00 Rapid move
- G01 Feed Rate move
- G02 Clockwise move
- G03 Counter Clockwise move
- G70 Inch mode
- G71 Millimeter mode
- G90 Absolute mode
- G91 Incremental mode
- G92 Home coordinate reset
- G94 Per minute feed
- G95 Per revolution feed
- M02 End of Program
- M03 Spindle On Clockwise, Laser, Flame, Power ON
- M04 Spindle On Counter Clockwise
- M05 Spindle Stop, Laser, Flame, Power OFF
- M06 Tool Change
- M08 Coolant On
- M09 Coolant Off
- M100 Machine Zero Reset

\*\*\*\*\*