
<i>Seat No.: Enrolment No.</i> _

GUJARAT TECHNOLOGICAL UNIVERSITY BE- VIIth SEMESTER-EXAMINATION - MAY/JUNE- 2012

Subject code: 172501 Date: 24/05/201 Subject Name: Computer Aided Manufacturing			
Time: 02:30 pm – 05:00 pm Total Ma Instructions:			rks: 70
	Atte Mak	ONS: mpt all questions. te suitable assumptions wherever necessary. tres to the right indicate full marks.	
Q.1	(a)	Justify the role of CAM in present day competitive manufacturing that	07
	(b)	has emerged out in Indian industries. Define NC, CNC and DNC machine. Write the advantages and disadvantages of CNC machines.	07
Q.2	(a)	Explain various stages involved with NC manufacturing. How do they differ from conventional manufacturing?	07
	(b)	What do you understand by NC coding? Explain the ISO and EIA standard codes for NC coding.	07
		OR	
	(b)	Explain the construction and working of an incremental optical encoder with the help of neat sketch.	07
Q.3	(a)	What does component drawing instruction decide? List type of formats used for NC/CNC programming.	07
	(b)	Why feedback necessary in machine tools? Discuss the methods used for position and velocity feedback in CNC machines.	07
0.1	()	OR	0.7
Q.3	(a)	Explain with neat Axis Identification in NC/CNC machines. Draw Axis Identification for lathe and milling machines.	07
	(b)	Prepare the manual part programming for components shown in fig.1	07
Q.4	(a)	Explain the role of Mechatronics in manufacturing. Write its	07
	(b)	advantages and disadvantages. Define Robot. Explain in brief the factors to be considered before introduction of robot in an organization.	07
		OR	
Q.4	(a)	Define CIM .Explain the various elements of CIM.	07
	(b)	List the CIM Hardware and software. Write the benefits of CIM.	07
Q.5	(a)	What is FMS? Discuss suitability of FMS and Problem faced in implementing FMS.	07
	(b)	Explain AGVs with neat sketch.	07
	ν-)	OR	
Q.5	(a)	What is CAPP? Explain in detail.	07
-	(b)	What is Rapid Prototyping? Explain Selective Laser Sintering.	07



G-Code

- G00 positioning (rapid traverse)
- G01 linear interpolation (feed)
- G02 circular interpolation CW
- G03 circular interpolation CCW
- G04 dwell
- G07 imaginary axis designation
- G09 exact stop check
- G10 offset value setting
- G17 XY plane selection
- G18 ZX plane selection
- G19 YZ plane selection
- G20 input in inch
- G21 input in mm
- G22 stored stroke limit ON
- G23 stored stroke limit OFF
- G27 reference point return check
- G28 return to reference point
- G29 return from reference point
- G30 return to 2nd, 3rd & 4th ref. Point
- G31 skip cutting
- G33 thread cutting
- G40 cutter compensation cancel
- G41 cutter compensation left
- G42 cutter compensation right
- G43 tool length compensation + dir
- G44 tool length compensation dir
- G49 tool length compensation cancel
- G45 tool offset increase
- G46 tool offset decrease
- G47 tool offset double increase
- G48 tool offset double decrease
- G50 scaling OFF
- G51 scaling ON
- G52 local coordinate system setting
- G54 work coordinate system 1 select
- G55 work coordinate system 2 select
- G56 work coordinate system 3 select
- G57 work coordinate system 4 select
- G58 work coordinate system 5 select

G59 work coordinate system 6 select

G60 single direction positioning

G61 exact stop check mode

G64 cutting mode

G65 custom macro simple call

G66 custom macro modal call

G67 custom macro modal call cancel

G68 coordinate system rotation ON

G69 coordinate system rotation OFF

G73 peck drilling cycle

G74 counter tapping cycle

G76 fine boring

G80 canned cycle cancel

G81 drilling cycle, spot boring

G82 drilling cycle, counter boring

G84 tapping cycle

G85,G86 boring cycle

G87 back boring cycle

G88,G89 boring cycle

G90 absolute programming

G91 incremental programming

G92 programming of absolute zero point

G94 per minute feed

G95 per revolution feed

G96 constant surface speed control

G97 constant surface speed control cancel

G98 return to initial point in canned cycle

G99 return to Ref point in canned cycle

M-Code

M00 program stop

M01 optional stop

M02 end of program (no rewind)

M03 spindle CW

M04 spindle CCW

M05 spindle stop

M06 tool change

M07 mist coolant ON

M08 flood coolant ON

M09 flood coolant OFF

M10 Clamps on

M11 Clamps off

M19 spindle orientation ON

M30 end program (rewind stop)

M98 call sub-program

M99 end sub-program