

GUJARAT TECHNOLOGICAL UNIVERSITY**ME Semester –I Examination Feb. - 2012****Subject code: 712803N****Date: 17/02/2012****Subject Name: Production Automation & CNC Technology****Time: 10.30 am – 01.00 pm****Total Marks: 70****Instructions:**

1. Attempt all questions.
2. Make suitable assumptions wherever necessary.
3. Figures to the right indicate full marks.

- Q.1** (a) Define various automation and discuss the various types of automation. Give atleast one example of each. **07**
 (b) Make a case study of implementing the automation system in casting industries. **07**
- Q.2** (a) Discuss the various CNC control systems with example. **07**
 (b) Explain the open loop control system and closed loop control system. **07**
- OR**
- (b) Give comparison between absolute and incremental co-ordinate system. **07**
- Q.3** (a) Enlist the various input media of NC machine and explain any one of them in detail. **07**
 (b) Explain various tape programming formats. **07**
- OR**
- Q.3** (a) Define interpolators. Describe the flow chart of software DDA interpolator for Linear interpolator and Circular interpolator. **07**
 (b) Explain the Geometric, Motion and Post processor statements in APT. **07**
- Q.4** (a) Explain Canned drilling cycle. **07**
 (b) What do you mean by Adaptive control? Discuss the Adaptive Controls Optimisation (ACO) system diagram for turning centre. **07**
- OR**
- Q.4** (a) Explain Double nut pre-loading method and Single nut pre-loading methods of ball-screw nut. **07**
 (b) Discuss the comparison between manual and computer aided part programming. **07**
- Q.5** (a) Write a manual part programme for finishing a forged component as shown in fig. 2. The speed and feed on the turning centre are 200 rpm and 0.35 mm/rev. Assume 1 mm material is to be removed radially from external diameter. **07**
 (b) Write a complete a part program for machining the forged component as shown in fig. 1 **07**
- OR**
- Q.5** (a) Write a complete APT part programme to turn a shaft as shown in fig. 3. The post processor call statement is MACHINE/CAST, 1. The tool used has a nose radius of 3mm. Assume spindle speed as 300 rpm and feed for machining as 0.3 mm/rev. **10**
 (b) Shot note on level of automation. **04**




Fig. 1




Fig. 2




Fig. 3