

Seat No.: _____

Enrolment No. _____

GUJARAT TECHNOLOGICAL UNIVERSITY

Diploma Semester -III Examination January- 2010

Subject code: 332902

Subject Name: Weaving Technology -I

Date: 23 / 01 / 2010

Time: 11.00 am- 1.30 pm

Total Marks: 70

Instructions:

1. Attempt all questions.
2. Make suitable assumptions wherever necessary.
3. Figures to the right indicate full marks.
4. English version is Authentic

Q.1	(a) Draw passage of yarn through loom.	07
	(b) State primary and secondary motion of loom.	07
Q.2	(a) Explain shedding motion.	07
	(b) Explain importance of winding process.	07
	OR	
	(b) Explain passage of yarn through high speed winding m/c.	07
Q.3	(a) Explain seven wheel take up motion.	07
	(b) Explain weft stop motrion.	07
	OR	
Q.3	(a) Explain loose reed stop motion.	07
	(b) Give causes and remedies of any two fabric defects.	07
Q.4	(a) Explain any two tensioners.	07
	(b) Explain any two slab catcher.	07
	OR	
Q. 4	(a) Give causes and remedies of any two package defects	07
	(b) Calculate production of winding m/c in Lb & Kg.from the following Speed : 1000 ypm , effi.: 80% , Ne. :50 , Time :8 hr. , no of Sp.: 60	07
Q.5	(a) Explain passage of yarn through high speed warping m/c.	07
	(b) Explain pirn winding m/c	07
	OR	
Q.5	(a) Explain any one dobby.	07
	(b) Calculate production of Loom in yard.from the following Speed : 200 RPM , effi.: 80% , , Time :8 hr. , picks/inch.: 72	07

સૂચના:

		1. તમામ પાંચ પ્રશ્નોના જવાબ ફરજીયાત છે.	
		2. જરૂર જણાય ત્યાં યથાયોજય ધારકાઓ બાંધવી.	
		3. જમણી બાજુ દશોવૈલ આંકડા પ્રશ્નોના પૂરા ગુણ દર્શાવે છે.	
		4. અંગેજી પત્ર આધારભૂત ગણાશે.	
પ્ર.૧	અ	લૂમ મા સુતર નો માર્ગ દોરો.	07
	બ	લૂમ ની પ્રાઇમરી અને સેકન્ડરી મોસન લખો.	07
પ્ર.૨	અ	શેડિંગ મિકેનીજમ સમજાઓ.	07
	બ	વાઇન્ડિંગ પ્રોસેસ ની અગત્યતા સમજાઓ. અથવા	07
	બ	હાઇ સ્પીડ વાઇન્ડિંગ મશીન મા સુતર નો માર્ગ સમજાઓ.	07
પ્ર.૩	અ	સેવન વ્હીલ ટેક અપ મોસન સમજાઓ.	07
	બ	વેફ્ટ સ્ટોપ મોસન સમજાઓ. અથવા	07
પ્ર.૩	અ	લૂજ રીડ મોસન સમજાઓ.	07
	બ	ગમે તે બે કાપડ ની ખામીઓ ના કારાણો તથા ઉપાયો લખો.	07
પ્ર.૪	અ	ગમે તે બે ટેંસનર સમજાઓ.	07
	બ	ગમે તે બે સ્લબ કેચર સમજાઓ. અથવા	07
પ્ર.૪	અ	ગમે તે બે પેકેજ ની ખામીઓ ના કારાણો તથા ઉપાયો લખો.	07
	બ	નીચેની વીગતો પરથી વાઇન્ડિંગ મશીન નું ઉત્પાદન રતલ તથા કીગ્રા મા સોધો. સ્પીડ : ૧૦૦૦ વાય પી એમ. કાર્યક્ષમતા : ૮૦% , કાઉટ : ૫૦ , સમય: ૮ કલાક , સ્પાંડલ ની સંખ્યા : ૫૦	07
પ્ર.૫	અ	હાઇ સ્પીડ વાર્પિંગ મશીન મા સુતર નો માર્ગ સમજાઓ.	07
	બ	પર્ન વાઇન્ડિંગ મશીન સમજાઓ. અથવા	07
પ્ર.૫	અ	ગમે તે એક ડોબી સમજાઓ.	07
	બ	નીચેની વીગતો પરથી લૂમ નું ઉત્પાદન વાર મા સોધો. સ્પીડ: ૨૦૦ આર પી એમ. , કાર્યક્ષમતા : ૮૦% , સમય : ૮ કલાક પીક્સ/ઇંચ : ૭૨	07
