

GUJARAT TECHNOLOGICAL UNIVERSITY**DIPLOMA ENGG.- I/IInd SEMESTER-EXAMINATION –JUNE/JULY- 2012****Subject code: 320020****Date: 30/06/2012****Subject Name: S.Q.C. in Textile****Time: 10:30 am – 01:00 pm****Total Marks: 70****Instructions:**

1. Attempt all questions.
2. Make suitable assumptions wherever necessary.
3. Figures to the right indicate full marks.
4. English version is considered to be Authentic

Q.1	(a) Write down the use of SQC in textile industry.	07
	(b) Draw a Bar chart with following data. 0-10 10-20 20-30 30-40 40-50 50-60 60-70 70-80 2 10 17 25 27 21 13 4	07
Q.2	(a) Calculate the mean from following data. 0-10 10-20 20-30 30-40 40-50 50-60 60-70 70-80 3 14 28 20 17 10 4 4	07
	(b) Calculate the mean by sorting method using above data.	07
	OR	
	(b) Write a short note on F- test.	07
Q.3	(a) Find out the mean with the help of following data. Number of days- 0 1 2 3 4 5 6 7 Number of family- 8 13 21 30 18 06 03 01	07
	(b) Give a definition of mean, median and mode and write down the formula for mean.	07
	OR	
Q.3	(a) Calculate the median from following data. Daily income- 150-160 160-170 170-180 180-190 190-200 200-210 No. of family- 05 18 33 17 15 12	07
	(b) Explain any 10 SI units for textiles	07
Q.4	(a) Calculate the median with following data 40-43 44-47 48-51 52-55 56-59 60-63 5 17 25 18 13 10	07
	(b) By tossing a dais 10 times , calculate the probability of getting '6' four times.	07
	OR	
Q. 4	(a) Calculate the value of Q1 and Q3 from the following data. Class-8-16 16-24 24-32 32-40 40-48 48-56 56-64 Frq. - 7 9 20 14 20 20 10	07
	(b) Write a short note on Poision distribution.	07
Q.5	(a) While checking the yarn we are getting following data. 40 43 41 40 42 43 48 44 39 40 Calculate the CV %age and S.D. from above data	07
	(b) If mean and variance of Binomial distribution is 3.2 and 1.92 respectively then find out number of events and probability.	07

OR

- Q.5** (a) In a factory while checking 40 items are found defective from 1000 items. If randomly 100 samples are taken then find out the probability of having 3 or more items are defective in sample.
Take $e^{-4} = 0.0183$ 07
 (b) The number of defect in 10 samples of fabric one meter each as follows. 07

$$\begin{array}{cccccccccc} 2 & 4 & 5 & 3 & 6 & 4 & 2 & 3 & 5 \end{array}$$

 With the help of C chart find out where the process is under control or not?

- પ્રશ્ન-૧** અ SQC નો ટેક્ષાઇલ માં ઉપયોગો સમજાવો. 07
 બ નિચેની રકમ માટે બાર ચાર્ટ દોરો 07

$$\begin{array}{cccccccccc} 0-10 & 10-20 & 20-30 & 30-40 & 40-50 & 50-60 & 60-70 & 70-80 \\ 2 & 10 & 17 & 25 & 27 & 21 & 13 & 4 \end{array}$$
- પ્રશ્ન-૨** અ નિચેની રકમ માટે મધ્યક શોધો. 07

$$\begin{array}{cccccccccc} 0-10 & 10-20 & 20-30 & 30-40 & 40-50 & 50-60 & 60-70 & 70-80 \\ 3 & 14 & 28 & 20 & 17 & 10 & 4 & 4 \end{array}$$

 બ ઉપરની રકમ માટે શોર્ટોગ પદ્ધતી થી મધ્યક શોધો. 07
 અથવા
 બ F-ટેસ્ટ વિશે ટુંકનોધ લખો. 07
- પ્રશ્ન-૩** અ નિચેના ડેટા પરથી મધ્યક શોધો. 07
 દિવસ- 0 1 2 3 4 5 6 7
 પરિવાર- 8 13 21 30 18 06 03 01
 બ મધ્યક, મધ્યસ્થ અને બહુલક ની વ્યાખ્યા લખો અને મધ્યક શોધવા માટે નુસુત્ર લખો. 07
 અથવા
- પ્રશ્ન-૪** અ નિચેની રકમ માટે મધ્યસ્થ શોધો 07
 દેનિક આવક- 150-160 160-170 170-180 180-190 190-200 200-210
 પરિવાર - 05 18 33 17 15 12
 બ કોઈપણ 10 SI યુનિટ લખો 07
- પ્રશ્ન-૫** અ નિચેની રકમ માટે મધ્યસ્થ શોધો 07

$$\begin{array}{cccccccccc} 40-43 & 44-47 & 48-51 & 52-55 & 56-59 & 60-63 \\ 5 & 17 & 25 & 18 & 13 & 10 \end{array}$$

 બ એક પાસા ને જ્યારે 10 વાર ઉછાડવા મા આવે ત્યારે ચાર વાર 6 આવવા ની સંભાવના શોધો. 07
- અથવા
- પ્રશ્ન-૬** અ નિચેની રકમ માટે Q1 અને Q3 ની કિંમત શોધો. 07
 Class-8-16 16-24 24-32 32-40 40-48 48-56 56-64
 Frq. - 7 9 20 14 20 20 10
 બ પોયસન ડિસ્ટ્રિબ્યુસન પર ટુંકનોધ લખો. 07

- અ યાર્ન ના એકિંગ વખતે નિચેના ડેટા મળે છે. 07
 41 43 41 40 42 43 48 44 39 40
 આના માટે $CV\%$ અને S.D. શોધો.
- બ જયારે દ્વિપદી વિતરણ મા મધ્યક અને મધ્યસ્થ અનુક્રમે 3.2 અને 1.92 છે 07
 તો ઘટના ઓ ની સંખ્યા અને સંભાવના શોધો.

અથવા

- અ એક ફેક્ટરી માં 1000 માં થી 40 વસ્તુઓ ખરાબ માલુમ પડે છે. જો 07
 યાદ્યાંક રિટે 100 સેમ્પલ લેવામા આવે તો તેમાંથી 3 થી વધારે વસ્તુ
 ખરાબ હોવાની સંભાવના કેટલી.
 Take $e^{-4} = 0.0183$
- બ 10 એક મિટર ના સેમ્પલ મા ખામીઓ નિચે મુજબ છે 07
 3 4 5 3 6 4 2 3 5
 C ચાર્ટ ની મદદ થી પ્રક્રિયા કંટ્રોલ મા છે કે નહી તે કે જણાવો.
