

Seat No.: _____

Enrolment No. _____

GUJARAT TECHNOLOGICAL UNIVERSITY
Diploma Engineering Semester –V Examination Dec'11- Jan'12

Subject code: 351702

Date: 22/12/2011

Subject Name: Process Instrumentation-II

Time: 10.30 am – 01.00 pm

Total Marks: 70

Instructions:

1. Attempt all questions.
2. Make suitable assumptions wherever necessary.
3. Figures to the right indicate full marks.
4. English version is considered Authentic.

- Q.1** (a) Explain Ultrasonic thermometer. What are its limitations? **07**
(b) Explain construction working and application of thermistor. **07**
- Q.2** (a) What is Pt-100 & its meaning?. Also explain lead wire compensation of RTD. **07**
(b) State various methods cold junction compensation of thermocouple and Explain one of them. **07**
- OR**
- Q.3** (b) Compare Thermistor, RTD & Thermocouple on common criteria. **07**
(a) Explain Displacer type level switch. **07**
(b) Explain capacitance method of level measurement with neat sketch. **07**
- OR**
- Q.3** (a) Explain one optical method of level measurement with neat sketch. **07**
(b) Explain motion balance type pneumatic level transmitter. **07**
- Q.4** (a) Explain strain gauge torsion-meter with diagram. **07**
(b) Define torque. Explain electrical torsion meter. **07**
- OR**
- Q. 4** (a) What is piezo-electric sensor ? Explain how it is used to measure vibration. **07**
(b) Explain elastic force meter with application. **07**
- Q.5** (a) Describe the construction and working of infrared radiation pyrometer and state its application, merits & demerits. **07**
(b) Explain various effects related with filled system. **07**
- OR**
- Q.5** (a) Classify filled system according SAMA and describe liquid filled system . **07**
(b) Explain fiber optic temperature system **07**

પ્રશ્ન-૧	અ	અલ્ટ્રાસોનીકથમોમીટર સમજાવો અને તેની મર્યોદા જણાવો.	07
	બ	થમોકપલની રચના કાર્ય અને તેની ઉપયોગીતા સમજાવો.	07
પ્રશ્ન-૨	અ	પી.ટી-૧૦૦ એ શું છે અને તેનો અર્થ શુ છે. અને તેનું લીડ વાયર કમ્પેસેસન સમજાવો.	07
	બ	થમોકપલની કોલ્ડ જંકશન કમ્પેસેસનની વિવિધ રીતો જણાવો અને તેમની એક રીત સમજાવો.	07
અથવા			
	બ	સામાન્ય પરિબળોથી થમોકપલ થમોકપલ અને આર.ટી.ડી ની સરખામણી કરો.	07
પ્રશ્ન-૩	અ	ડીસ્પ્લેસર લેવલ સ્વીચ સમજાવો.	07
	બ	સ્વચ્છ આકૃતિની મદદથી લેવલ માપનની કેપેસિટંસ પધ્ધતિ સમજાવો.	07
અથવા			
પ્રશ્ન-૩	અ	સ્વચ્છ આકૃતિની મદદથી લેવલ માપનની પ્રકાશીયપધ્ધતિ સમજાવો.	07
	બ	મોશન બેલેંસ ટાઇપ ન્યુમેટીક લેવલ ટ્રાંસમિટર સમજાવો.	07
પ્રશ્ન-૪	અ	ડાયાગ્રામ સાથે સ્ટ્રેન-ગેજ ટોર્શન મિટર સમજાવો.	07
	બ	ટોર્કની વ્યાખ્યા આપી ઇલેક્ટ્રિક ટોર્શન મિટર સમજાવો.	07
અથવા			
પ્રશ્ન-૪	અ	પિજો- ઇલેક્ટ્રિક સંવેદક એટ્લે શું. તેનાથી કેવી રીતે કમ્પન મપાય છે તે સમજાવો.	07
	બ	ઉપયોગીતાથી ઇલાસ્ટિક ફોર્સ મિટર સમજાવો.	07
પ્રશ્ન-૫	અ	ઇંફારેડ રેડીએશન ટાઇપ પાયરોમીટરની રચના અને કાર્ય ઉપયોગીતા, ફાયદા અને ગેરફાયદા સમજાવો.	07
	બ	ભરેલ તંત્રની વિવિધ અસરો સમજાવો.	07
અથવા			
પ્રશ્ન-૫	અ	ભરેલ તંત્રનું SAMA મુજબ વર્ગીકરણ કરો અને પ્રવાહી ભરેલ તંત્ર વર્ણવો.	07
	બ	ફાઇબર ઓપ્ટીક તાપમાન તંત્ર સમજાવો.	07
