

Seat No.: \_\_\_\_\_

Enrolment No. \_\_\_\_\_

**GUJARAT TECHNOLOGICAL UNIVERSITY**  
**Diploma Engineering Semester –V Examination Dec'11- Jan'12**

**Subject code: 355205**

**Date: 30/12/2011**

**Subject Name: Quality Control**

**Time: 10.30 am – 01.00 pm**

**Total Marks: 70**

**Instructions:**

- 1. Attempt all questions.**
- 2. Make suitable assumptions wherever necessary.**
- 3. Figures to the right indicate full marks.**
- 4. English version is considered Authentic.**

<b>Q.1</b>	(a) Define Rational Analysis? Explain Importance of rational analysis.	<b>07</b>
	(b) What is Soluble Salt? Explain effect of Soluble Salt in manufacturing process of ceramic article.	<b>07</b>
<b>Q.2</b>	(a) Explain method of determine particle size distribution of material.	<b>07</b>
	(b) What is plasticity? How we can determine water of plasticity of clay.	<b>07</b>
	<b>OR</b>	
	(b) Describe method of determine flow rate of feldspar.	<b>07</b>
<b>Q.3</b>	(a) Define slip fluidity, rate of casting, moisture content.	<b>07</b>
	(b) What is Density? How it can control and affect slip properties.	<b>07</b>
	<b>OR</b>	
<b>Q.3</b>	(a) What is Shrinkage? Explain measuring drying and firing shrinkage.	<b>07</b>
	(b) Define MOR and Write down MOR determination Method.	<b>07</b>
<b>Q.4</b>	(a) What is spalling? How it affect quality of refractory.	<b>07</b>
	(b) Explain different types of porosity and its measurement process.	<b>07</b>
	<b>OR</b>	
<b>Q. 4</b>	(a) What is crazing? Write down crazing measuring process of tiles.	<b>07</b>
	(b) Write a short note on Bloating and Crowling.	<b>07</b>
<b>Q.5</b>	(a) Write the effect of electrolytes on fluidity of casting slip.	<b>07</b>
	(b) Describe the process to determine the PCE of Refractory bricks.	<b>07</b>
	<b>OR</b>	
<b>Q.5</b>	(a) Write down the precautions required to control dunting defect in sanitary ware.	<b>07</b>
	(b) Explain use of computer to improve quality control of Products.	<b>07</b>

\*\*\*\*\*

પ્રશ્ન-૧	અ રેશનલ સંશોધન પ્રક્રિયાની વ્યાખ્યા આપો અને તેનું મહત્વ વર્ણવો.	07
	બ સોલ્યુબલ સોલ્ટ એ શું છે? સીરામિક પેદાશો બનાવતી વખતે સોલ્યુબલ સોલ્ટની થતી અસર વર્ણવો.	07
પ્રશ્ન-૨	અ મટીરીયલનું કદનાં આધારે પૃથ્વીકરણ શોધવાની પદ્ધતી વર્ણવો.	07
	બ ચીકાસતા એ શું છે? માટીની ચીકાસતા શોધવાની પદ્ધતી વર્ણવો.  અથવા	07
	બ ફેલ્સપારનો વહન દર શોધવાની પદ્ધતી વર્ણવો.	07
પ્રશ્ન-૩	અ સ્લીપની વહનતા, સ્લીપ જમવાનો દર અને ભેજનાં પ્રમાણની વ્યાખ્યા આપો.	07
	બ ઘનતા એ શું છે? તે કેવી રીતે કાબુમાં લેવાય છે? અને તે સ્લીપનાં ગુણધર્મોને કેવી રીતે અસર કરે છે?	07  અથવા
પ્રશ્ન-૪	અ સંકોચન એ શું છે? સુકવણી સંકોચન અને પકવણી સંકોચન વર્ણવો.	07
	બ MOR ની વ્યાખ્યા આપો. અને MOR શોધવાની પદ્ધતી લખો.	07
પ્રશ્ન-૫	અ “સ્પાલીંગ” એ શું છે? ઉશ્માસહની ગુણવત્તા ઉપર તે કેવી રીતે અસર કરે છે?	07
	બ જુદા જુદા પ્રકારની છીકાળુતાં અને તેને શોધવાની પદ્ધતી વર્ણવો.	07  અથવા
પ્રશ્ન-૬	અ “કેઝીંગ” એ શું છે? “કેઝીંગ” તપાસવાની પદ્ધતી વર્ણવો.	07
	બ “બ્લોટીંગ” અને “કાઉલીંગ” ઉપર ઢ્રેકનોંધ લખો.	07
પ્રશ્ન-૭	અ કાસ્ટીંગ સ્લીપની વહનતાં ઉપર થતી ઇલેક્ટ્રોલાઇટની અસર વર્ણવો.	07
	બ ઉશ્માસહ ઇટનું પીસીએ મુલ્ય શોધવાની પદ્ધતી વર્ણવો.	07  અથવા
પ્રશ્ન-૮	અ સનેટરીવેરમાં “ડંટીંગ” ખામીને કાબુમાં રાખવા માટે લેવા પડતા સાવચેતીનાં પગલાઓ લખો.	07
	બ પેદાશોની ગુણવત્તા સુધારવા માટે કમ્પ્યુટરનો ઉપયોગ વર્ણવો.	07

\*\*\*\*\*