

GUJARAT TECHNOLOGICAL UNIVERSITY
DIPLOMA ENGINEERING - SEMESTER-V • EXAMINATION – SUMMER 2013


Subject Code: 352404**Date: 21-05-2013****Subject Name: Control system****Time: 10:30 am - 01:00 pm****Total Marks: 70****Instructions:**

1. Attempt all questions.
2. Make suitable assumptions wherever necessary.
3. Figures to the right indicate full marks.
4. English version is considered to be Authentic.

Q.1 (a) Draw a block diagram of closed loop control system and Derive Transfer function for it. **07**

(b) Explain Construction operation and characteristics of DC servomotor **07**

Q.2 (a) Find the transfer function of the given circuit. **07**



(b) Explain Transfer function of R-L-C series Network with circuit diagram. **07**

OR

(b) The transfer function of a system is given by $\frac{s(s+2)(s+4)}{s(s+1)(s^2+4s+8)}$. Determine the pole – zero and show the pole zero configurations in s-plane. **07**

Q.3 (a) Explain with neat sketch. **07**


(1) Step signal (2) Ramp signal(3)impulse signal

(b) Explain time response of a first order control system subjected to unit step response with block diagram. **07**

OR

Q.3 (a) Draw transient response of second order control system and define maximum overshoot. **07**

(b) The block diagram of unity feedback control system is shown in fig. **07**



Determine the maximum overshoot and natural frequency of oscillation.

Q.4 (a) Define stability and relative stability. Write necessary condition for stability. **07**

(b) Draw time response and location of roots in case of stable, marginally stable and unstable system **07**

OR

Q. 4 (a) Determine the stability of the system whose characteristic equation is $s^4 + 10s^3 + 30s^2 + 100s + 25 = 0$ **07**


- (b) For the characteristic equations $s^4 + 7s^3 + 10s^2 + k=0$, determine the limiting value of k for stability. **07**
- Q.5** (a) Explain effect of proportional, derivative and integral control action On system performance. **07**
(b) Explain construction and operation of AC Tachometer. **07**
OR
- Q.5** (a) Explain block diagram and working principle of AC position control system: **07**
(b) Describe proportion control system with suitable example and block diagram. **07**

ગુજરાતી

પ્રશ્ન. ૧ અ કલોજ લુપ કન્ટ્રોલ સીસ્ટમ નો નોબ્લોક ડાયાગ્રામ દોરી તેનું ટ્રાંસ્ફર ફનક્શન ૦૭ મેળવો.

બ મોટર નું બંધારણ, કાર્ય અને સિદ્ધાંત સમજાવો. ૦૭

પ્રશ્ન. ૨ અ નીચેના પરીપથ માટે ટ્રાંસ્ફર ફનક્શન શોધો. ૦૭



બ R-L-C સીરીઝ નેટ્વર્ક માટે ટ્રાંસ્ફર ફનક્શન સોધો. ૦૭

અથવા

બ સિસ્ટમદ્વારાનું ટ્રાંસ્ફર ફનક્શન $\frac{20(s+3)(s+4)}{(s+1)(s+2)(s+5)}$ દ્વારા આપેલું છે. તેના માટે પોલ ઝીરો નક્કી કરો અને તેના માટે લોકેશન દોરો.

પ્રશ્ન. ૩ અ સ્વચ્છ આકૃતી સાથે નીચેના સમજાવો. ૦૭

1. સ્ટેપ સિગનલ

2. રેમ્પ સિગનલ


3. ઈંપલ્સ સિગનલ

બ બ્લોકડાયાગ્રામસાથેયુનીટ સ્ટેપ અધીનયુનિટી ફિડબેક નિયંત્રણસિસ્ટમનો સમયપ્રતિબાવસમજાવો. ૦૭

અથવા

પ્રશ્ન. ૩ અ સેકન્ડ ઓર્ડર સીસ્ટમ માટે ટ્રાંઝિયંટ રીસ્પોસ દોરો. અને મેક્સીમમ ઓવરસુટ વ્યાખ્યાયીત કરો.

બ નીચે આપેલી યુનિટી ફિડબેક કન્ટ્રોલ સીસ્ટમ માટે મેક્સીમમ ઓવરસુટ અને નેચરલ ફીકવંસી ઓફ ઓસીલેસન શોધો.



પ્રશ્ન. ૪ અ સ્ટેબિલિટી અને સબ્સ્ટીટ્યુટ સ્ટેબિલિટી વ્યાખ્યાયીત કરો. સ્ટેબિલિટી માટે જરૂરી સ્થીતીઓ લખો. ૦૭

બ સ્ટેબલ, અન્સ્ટેબલ અને માર્જિનલી સ્ટેબલ સીસ્ટમ ના કીસ્સા મા ટાઈમ રીસ્પોસ ૦૭

અને કુટ લોકેશન દોરે.

અથવા

પ્રશ્ન. ૪ અ લાક્ષણિકતાસમીકરણ $r^4 + 10r^3 + 30r^2 + 100r + 25 = 0$ માટે સ્ટેબીલિટી નક્કી ૦૭ કરો.

બ લાક્ષણિક સમીકરણ $r^4 + 7r^3 + 10r^2 + k=0$, ની સ્ટેબીલિટી માટે k ની મર્યાદીત ૦૭ કીમત નક્કી કરો.

પ્રશ્ન. ૫ અ પ્રપોશનલ ડેરિવેટીવ અનેઇંગ્રાલ કંન્ટ્રોલ ની સીસ્ટમ પરફોરમન્સ પર ૦૭ થતી અસરો સમજાવો.

બ એ. સી. ટેકોમીટર નું કન્સ્ટ્રક્શનદોરી તેનું ઓપરેશન સમજાવો. ૦૭

અથવા

પ્રશ્ન. ૫ અ એ. સી. પોઝિશન કંટ્રોલ સિસ્ટમ બંધપરિપથ સાથે સમજાવો. ૦૭

બ પ્રપોજનલ કંટ્રોલસીસ્ટમ ચોગ્ય ઉદાહરણ અને બ્લોક ડાયાગ્રામ સાથે સમજાવો ૦૭
